RECALL LIST - SUMMER 2023

Woom Bikes USA – Original Kids' Bicycles

The stem and handlebar on the bikes can detach and cause riders to lose control, posing a fall hazard.

<u>Infanttch Zooby Video Baby Monitors for Cars</u>

The baby monitor's battery can malfunction, overheat and burst, posing a fire hazard.

CaTeam Canvas Baby Hammock Swing

The inclined sleeper is a banned hazardous product under the Safe Sleep for Babies Act since the product was marketed for infant sleep and has an incline angle greater than 10 degrees. Infant fatalities have occurred in inclined sleepers after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances.

Sound Around Children's Multi-Purpose Helmet

The recalled helmets do not comply with the positional stability requirements of the U.S. CPSC federal safety standard for bicycle helmets. The helmets can fail to protect in the event of a crash, posing a risk of head injury.

Zuru Baby Shark and Mini Baby Shark Bath <u>Toys</u>

When using the recalled bath toys, particularly in a bathtub or wading pool, a child can slip and fall or sit onto the hard plastic top fin of the shark, posing risks of impalement, lacerations and punctures.

TopGlore Narskido Infant Bath Seat

The bath seats fail to meet the federal safety standard for infant bath seats, including requirements for stability and leg openings, and can tip over while in use, posing a drowning hazard to babies.

The Good and Beautiful Math 1 and Math 3 Boxes

The whiteboard attached to the boxes can become detached exposing sharp edges, posing a laceration hazard.

Juratoys Children's Activity Tables

The activity table contains a silver metal bell which can detach from its metal arch, posing a choking hazard to young children.

<u>CultureFly L.O.L. Surprise! Trick or Treat</u> <u>Subscription Boxes</u>

The paint on the children's metal doll pins contains levels of lead that exceed the federal lead paint ban, posing a lead poisoning hazard. Lead is toxic if ingested by young children and can cause adverse health effects.

Diamond Visions Plush Monkey Toys

The eyes on the toy can detach, posing a small part choking hazard to children.



<u>Lucky Global Lelinta Multi-Purpose Kids</u> Helmets

The recalled helmets do not comply with the positional stability requirements of the CPSC federal safety standard for bicycle helmets. The helmets can fail to protect a child in the event of a crash, posing a risk of head injury.

Lil Anglers Children's Fishing Rods

The fishing rods contain levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health issues.

<u>Delta Enterprise Corp. 2-in-1 Outdoor Kids</u> <u>Swing</u>

The swing seat restraint straps can break, posing a fall hazard to young children.

Mockingbird Single Stroller

The lower side of the stroller frame can crack, posing a fall risk to children in the stroller.

Meiling Hou Crib Bumpers

Infants can suffocate if they roll or move on the crib bumper in a position that obstructs breathing. Padded crib bumpers are banned under federal law.

Epoch Everlasting Play Calico Critters Figures and Sets with Bottle and Pacifier Accessories

The bottle and pacifier accessories pose a choking hazard to children.

Primark Children's Bamboo Plates

The recalled children's bamboo plates have elevated levels of lead and formaldehyde. Both lead and formaldehyde are toxic if ingested by children and can cause adverse health effects.

<u>Clark Associates Lancaster Table & Seating</u> High Chair

The high chairs can break, posing a fall hazard to children.

<u>Kids Preferred Recalls "My First" Disney-</u> <u>Character Figurine</u>

The arms or legs on the figurines can detach, posing a small part choking hazard to children.

Fisher Price Rock 'n Play Sleepers

Infant fatalities have occurred in the Rock 'n Play Sleepers, after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances.

Kids2 Rocking Sleepers

Infant fatalities have occurred in the Rocking Sleepers, after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances.

